

# Oil Field Environmental Incident Summary

**Incident:** 20150531121455 **Date/Time of Notice:** 05/31/2015 12:14

**Responsible Party:** CONTINENTAL RESOURCES, INC.

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** HAWKINSON 15-22H

**Field Name:** OAKDALE

**Well File #:** 31104

**Date Incident:** 5/31/2015

**Time Incident:** 04:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 147

**Rng:** 96

**Sec:** 22

**Qtr:**

**Location Description:**

**Submitted By:** NATE STANHOPE

**Received By:**

**Contact Person:** NATE STANHOPE  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	1.5	Barrels	1.5	Barrels		

**Description of Other Released Contaminant:**

Invert

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

N/A

**Areal Extent:**

***Potential Environmental Impacts:***

Location Soil

***Action Taken or Planned:***

Standing fluid was sucked up and hand tools will be used to remove impacted scoria.

***Wastes Disposal Location:*** Tanks on-site

***Agencies Involved:***

***Updates***

---

***Date:*** 6/1/2015      ***Status:*** Reviewed - Assigned to Other Agency      ***Author:*** Crowdus, Kory

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release remained on location according to the report. NDIC retains oversight.